



Bolivar Barge Cleaning Service, LLC

HOSE AND PIPELINE TESTS

VESSEL: Geosail 109 OFFICIAL #: 1045953

THE FOLLOWING ITEMS HAVE BEEN CHECKED AND TESTED IN ACCORDANCE WITH
46CFR 35.35-70 AND 33CFR 156.170 ON 2-15-2019
(Date)

Yes PRESSURE GAUGES HAVE BEEN CHECKED WITHIN 10% ACCURACY

NA EMERGENCY SHUTDOWN HAS BEEN CHECKED AND FOUND OPERABLE

NA TRANSFER SYSTEM RELIEF VALVE HAS BEEN TESTED AND CHECKED - 125 P.S.I.

Yes ALL TRANSFER PIPING SYSTEMS AND ASSOCIATED VALVES HAVE BEEN TESTED AND CHECKED AT 187.5 P.S.I.

Yes CARGO HOSE VISUALLY AND HYDROSTATICALLY TESTED TO 225 PSI

THE ABOVE ITEMS CHECKED, TESTED AND VERIFIED BY:

E. Blt