

BOLIVAR BARGE CLEANING SERVICES,LLC.

1415 RANKIN Rd.
Port Bolivar Tx.77650
409-925-8897

Consolid
109-116
CARGO HOSE TEST

**INSTRUCTIONS: ALL FIELDS ARE REQUIRED...USE N/A ON ANY NON-APPLICABLE LINE.
NOTE ALL TESTS ARE VALID FOR ONE YEAR FROM DATE OF TEST**

CARGO HOSE SERIAL/ ID NUMBER. NCO 0272

TEST DATE. 2-15-2019 TEST EXPIRATION DATE 2-15-2020

HOSE DIAMETER: 8" INCHES

HOSE LENGTH: 25 FEET

END FITTINGS A: Steel

END FITTINGS B: Steel

CONDITION OF HOSE COVER DURING INSPECTION GOOD FAIR POOR

CONDITION OF HOSE TUBE DURING INSPECTION GOOD FAIR POOR

OIL SERVICE MARK ON HOSE YES NO

HAZMAT SERVICE MARKED ON HOSE. YES NO

MAXIMUM ALLOWABLE WORKING PRESSURE MARKED ON HOSE. YES NO

MAWP MARKED ON HOSE. 150 PSI

HOSE TEST PRESSURE. 225 PSI

COMPANY/LOCATION OF TESTER Bayou Fleet

TEST CERTIFIED BY (PRINT) Emmanuel Boston

TEST CERTIFIED BY (SIGNATURE) *Emmanuel Boston* (DATE) 2-15-2019

The competent person's name and signature above certifies that testing of this cargo hose has been performed in accordance with USCG regulations Title 33 of Federal Register Chapter 1 U.S. Coast Guard Department of Transportation Par 154.500 Hose Assemblies. Par-156 subpart a- Oil and Hazardous Material Transfer Operations, 156.170 Equipment Test and Inspections:



Bolivar Barge Cleaning Service, LLC

HOSE AND PIPELINE TESTS

VESSEL: Gonsalia 110 OFFICIAL #: 1045954

THE FOLLOWING ITEMS HAVE BEEN CHECKED AND TESTED IN ACCORDANCE WITH
46CFR 35.35-70 AND 33CFR 156.170 ON 2-15-2019
(Date)

- Yes PRESSURE GAUGES HAVE BEEN CHECKED WITHIN 10% ACCURACY
- NA EMERGENCY SHUTDOWN HAS BEEN CHECKED AND FOUND OPERABLE
- NA TRANSFER SYSTEM RELIEF VALVE HAS BEEN TESTED AND CHECKED - 125 P.S.I.
- Yes ALL TRANSFER PIPING SYSTEMS AND ASSOCIATED VALVES HAVE BEEN TESTED AND CHECKED AT 187.5 P.S.I.
- Yes CARGO HOSE VISUALLY AND HYDROSTATICALLY TESTED TO 225 PSI

THE ABOVE ITEMS CHECKED, TESTED AND VERIFIED BY: